



# Workstation Specialists



## CONTACT SUPPORT

FREE PHONE:  
+44 0800 180 4801

EMAIL:  
SUPPORT@WKSMAIL.COM

## SYSTEM RECOVERY GUIDE

---

SYSTEM RECOVERY USB

# SET UP GUIDE

## STEP 1 - BOOT FROM USB RECOVERY KEY




- A: SHUTDOWN YOUR SYSTEM AND REMOVE ALL EXTERNAL HARD DRIVES.**
- B: INSERT THE USB RECOVERY KEY AND POWER ON SYSTEM. REPEATEDLY PRESS THE BOOT MENU KEY FOR YOUR SYSTEM.\***
- C: ONCE IN THE BOOT MENU NAVIGATE TO THE USB RECOVERY KEY AND PRESS ENTER.**

\*YOUR SYSTEMS BOOT MENU KEY IS OFTEN LISTED AT THE BOTTOM OF THE SCREEN WHEN YOUR SYSTEM IS TURNING ON. ALTERNATIVELY YOU CAN FIND YOUR SYSTEMS BOOT MENU KEY ON OUR WEBSITES FAQ'S:

[WWW.WORKSTATIONSPECIALIST.COM/FAQ](http://WWW.WORKSTATIONSPECIALIST.COM/FAQ)

## STEP 2 - PRIMARY DRIVE SELECTION




WAIT FOR THE RECOVERY UTILITY TO LOAD AS SHOWN ABOVE. YOU MAY BE PROMPTED TO PRESS 'ANY KEY TO BOOT FROM USB'. ENTER THE DRIVE NUMBER YOU WISH TO RESTORE TO AND PRESS ENTER.

**WARNING! USING THIS RESTORE UTILITY WILL ERASE ALL DATA ON THE SELECTED DRIVE.**

PLEASE ENSURE YOU HAVE BACKED UP ALL IMPORTANT DATA, INCLUDING RELEASING ANY SOFTWARE LICENCES BEFORE CONTINUING.

## STEP 3 - CONFIRM SELECTION




REVIEW YOUR DRIVE SELECTION AND ENTER 'Y' TO BEGIN YOUR SYSTEM RECOVERY.

**WARNING! USING THIS RESTORE UTILITY WILL ERASE ALL DATA ON THE SELECTED DRIVE.**


PLEASE ENSURE YOU HAVE BACKED UP ALL IMPORTANT DATA, INCLUDING RELEASING ANY SOFTWARE LICENCES BEFORE CONTINUING.

## STEP 4 - RESTORING



YOUR SYSTEM IS NOW RESTORING. PLEASE WAIT PATIENTLY FOR THE PROCESS TO COMPLETE. THIS MAY TAKE UP TO 30 MINUTES.

## STEP 5 - RESTORE COMPLETE & SHUTDOWN



YOU HAVE NOW SUCCESSFULLY RESTORED YOUR SYSTEM. REMOVE YOUR RECOVERY USB AND PRESS ANY KEY TO SHUTDOWN YOUR SYSTEM.

## STEP 6 - WINDOWS SET UP



POWER ON YOUR SYSTEM AND FOLLOW THE ON SCREEN INSTRUCTION TO COMPLETE THE WINDOWS SET UP WIZARD.